

Tips when specifying millwork

1. For cabinet locks, indicate “where shown”. If not shown on plans then mill worker is required to include locks on all cabinets.
2. For solid surfacing material, indicate color or color range. Manufacturers have several price points for different color groups for example solid color verses heavy inlayed particulate.
3. More to follow.....